



POOR GROUND
NOT SURVEYED

AG5


POOR GROUND
NOT SURVEYED

AG4

POOR GROUND
NOT SURVEYED

AG6

POOR GROUND
NOT SURVEYED




Project: Regional Wastewater Treatment Plant (WwTP),
Greater Dublin Drainage, North County Dublin

Figure:
Interpolated greyscales: Annsbrook, AG5 & AG6

Figure No: 11 Scale: 1/1500 @ A4 Ref: TAG 13003





POOR GROUND
NOT SURVEYED

NG5

NG1

POOR GROUND
NOT SURVEYED


NG2

NG3

NG4

NG6

N



Project: Regional Wastewater Treatment Plant (WwTP),
Greater Dublin Drainage, North County Dublin

Figure:
Interpolated greyscales: Newtowncorduff, NG4-NG6


Figure No: 14 Scale: 1/1500 @ A4 Ref: TAG 13003

POOR GROUND
NOT SURVEYED

NG7

NG8

NG9



Project: Regional Wastewater Treatment Plant (WwTP)
Greater Dublin Drainage, North County Dublin

Figure:
Interpolated greyscales: Newtowncorduff, NG7-NG8

Figure No: 15 **Scale:** 1/1500 @ A4 **Ref:** TAG 13003