







GROUND SURVEYED

POOR GROUND NOT SURVEYED

AG4

POOR GROUND NOT SURVEYED

AG6

Project: Regional Wastewater Treatment Plant (WwTP), Greater Dublin Drainage, North County Dublin

Figure: Raw (drift/median correction) greyscales: Annsbrook, AG4


Figure No: 22 Scale: 1/1500 @ A4 Ref: TAG 13003





AG7

POOR GROUND
NOT SURVEYED



Project: Regional Wastewater Treatment Plant (WwTP),
Greater Dublin Drainage, North County Dublin

Figure: Raw (drift/median correction) greyscales:
Annsbrook, AG7

Figure No: 24 **Scale:** 1/1500 @ A4 **Ref:** TAG 13003