



- Key**
- Proposed Project Boundary
 - Baseline Vibration Monitoring Location

Copyright © Ordnance Survey Ireland. Licence number 3/3/34/Irish Water.
 Service Layer- Sources: Esri, HERE, DeLorme, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), MapmyIndia, NGCC, © OpenStreetMap contributors, and the GIS User Community



| | | | | | | |
|------|------------|---------------------|-------|---------|-------|-------|
| 0 | 08/06/2018 | FINAL | RG | SmG | PW | CoK |
| Rev. | Date | Purpose of revision | Drawn | Check'd | Rev'd | Apprd |



Client

Project Greater Dublin Drainage Project

Drawing Title **Figure 15.2 Vibration Monitoring Locations at Connolly Hospital**

Drawing Status **FINAL**

Scale @A3 1:5,000
 Jacobs No. 32102902

Drawing No. 32102902-EIAR-1502

This drawing is not to be used in whole or in part other than for the intended purpose and project as defined on this drawing. Refer to the contract for full terms and conditions.

